

PROTOCOL FOR CLEANING OR MAINTENANCE WORKS IN RADIOACTIVE FACILITIES

- All external workers are required to collaborate with the radiation protection manager, both of their company and of the owner of the facility, in their protection against ionizing radiation, complying with the standards established by them.
- Non-authorized personnel who must access radioactive facilities to carry out any maintenance or cleaning work, the person in charge/supervisor must be notified in advance.
- Only authorized personnel of the facility and authorized personnel of the external company that is going to carry out the intervention will have access to the radioactive facilities. The SUPERVISOR will indicate if it is possible to enter the laboratory.
- If it is possible to enter the laboratory, there will be no time restriction or additional protective measures, unless in an emergency, in which case the SUPERVISOR will indicate how to proceed. Then, the supervisor will notify the Radiation Protection Area and will take radiation and/or contamination measures.
- Prior to the entry of external workers in radiological areas, environmental radiation measurements will be taken and recorded in the DIARIO DE OPERACIONES, by the supervisor.

